

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri Ch.V.Subbaiah, B.Tech.,
Executive Engineer,
(R&B) Division,
Vijayawada.

To,
Secretary & Correspondent,
The Vijayawada Don Bosco Society,
Carmel Nagar, Gunadala,
Vijayawada-4.

Letter No. Structural Soundness Certificate/JTO2/2019, Dated: 07-01-2020

Sir,

Sub: - (R&B) Division, Vijayawada – The Vijayawada Don Bosco Society, Don Bosco School, D. No. 44-13/1-1/1, Carmel Nagar, Gunadala, Vijayawada - 4 – Soundness Certificate – Issued – Regarding.

Ref: - 1) Lr. No. Nil, Dt. 04-11-2019 of the Vijayawada Don Bosco Society, Don Bosco School, D. No. 44-13/1-1/1, Carmel Nagar, Gunadala, Vijayawada - 4.


It is informed that the **Don Bosco School**, located at **D. No. 44-13/1-1/1, Carmel Nagar, Gunadala, Vijayawada - 4** has inspected by Dy. Executive Engineer (R&B) Buildings sub division, along with Assistant Engineer (R&B) Buildings Section III, Vijayawada on 03-01-2020 and the said School building with the following instructions to the School management

1. The width of the staircase flight is 1.40 Mts. On north side and 1.10 Mts on south side staircase against required width of 1.50 Mts.
2. The thread width is 0.30 Mts. As against required of 0.30 Mts. and height of the rise is 0.15 Mts against required width of 0.15 Mts. in both staircases.
3. The height of the hand railing is 0.90 Mts @ Ground & First Floor as against 1.20 Mts.
4. The height of corridor parapet wall is 0.72 Mts. as against 1.20 Mts. (But above parapet wall open area is protected with iron grills)
5. The width of the corridor is 2.60 Mts. as against 2.50 Mts.

Hence, the School management is responsible to take necessary precautions and maintain the requirements.

However, it is Structurally Sound for a period of one year i.e., from 03-01-2020 to 02-01-2021 only.

Yours faithfully,



Executive Engineer
(R&B) Division, Vijayawada.